



# F. H. BRUN্ডLE

## PAINT PREPARATION SHEET



### **Preparation and Application:**

Ensure all surfaces are dry, clean and free from dirt, oil, grease and contamination. Where applicable, if existing coating is hard/glossy, abrade prior to application.

Internal non-porous substrates, e.g. previously painted, ceramic, ferrous metal, radiators etc. apply 1 coat of Ardenbrite QD Base Coat and 2 coats of Metallic Paint.

External non-porous substrates, e.g. previously painted, apply 1 coat of Ardenbrite QD Base Coat, 2 coats of Metallic Paint and 2 coats of Ardenbrite Glaze.

External untreated ferrous metal, apply an anti-corrosive primer, 2 coats of Metallic Paint and 2 coats of Glaze.

External galvanised steel, apply an etch primer, 1 coat of QD Base Coat, 2 coats of Metallic Paint and 2 coats of Glaze.

All products can be applied by brush, roller or spray. It is essential the metallic paint is thoroughly shaken and stirred, and frequently agitated during use.

**SOUTH & WEST**  
502 Millbrook Road,  
Third Avenue, Millbrook,  
Southampton,  
SO15 0JX  
Tel: 023 8070 3333  
Fax: 023 8070 5555

**NORTH WEST**  
Haydock Lane,  
Haydock Industrial Park,  
St. Helens,  
WA11 9XE  
Tel: 01942 86 88 88  
Fax: 01942 86 88 99

**LONDON & SOUTH EAST**  
Lamson Road,  
Ferry Lane North,  
Rainham, Essex,  
RM13 9YY  
Tel: 01708 25 35 45  
Fax: 01708 25 35 50

**WEST MIDLANDS**  
Unit 6, Dorset Road,  
Saltley Business Park,  
Saltley, Birmingham,  
B8 1BC  
Tel: 0121 327 8999  
Fax: 0121 327 85555

**EAST MIDLAND & NORTH**  
Condor Road,  
Quarry Hill Ind. Estate,  
Ilkeston,  
DE7 4RE  
Tel: 0115 930 2070  
Fax: 0115 951 2455

**SCOTLAND**  
37 St. Clair Street,  
Edinburgh,  
Scotland,  
EH6 8LB  
Tel: 0131 656 7400  
Fax: 0131 656 7499